



GHIERE QUICK CAPS QUICK CAPS



UGELLI TVI

Posizionare i fori di aspirazione aria in corrispondenza delle aperture sulla ghiera

TVI SPRAY TIPS

Position the air intake holes towards the ring nut openings

Pressione di esercizio max.: 25 bar (pressione max. ugelli impiegati)
Peso: 80.618.38 10.7 g - 84.618.51 11 g - 84.618.52 10.5 g

Materiali: materiale plastico ad alta resistenza - EPDM - PTFE

Impiego: su getti serie Quick Cap. Ideale per atomizzatori assiali a torretta. Ispezione e pulizia rapida degli ugelli. Modello **80.618.38**: allineamento automatico (10°) ugelli antideriva a ventaglio.

Max. operating pressure.: 25 bar (370 psi) (max. spray tips operating pressure)
Weight: 80.618.38 10.7 g (0.378 oz) - 84.618.51 11 g (0.388 oz) - 84.618.52 10.5 g (0.37 oz)

Materials: high resistance plastic material - EPDM - PTFE

Use: for agriculture use on Quick Cap nozzles models. Specific for axial fbw tower fan systems. Fast spray tips inspection and cleaning. **80.618.38** model: anti-drift flat fan spray tips automatic alignment (10°)

COME SI ORDINA / HOW TO ORDER

GHIERA + GUARNIZIONE cap + gasket	SOLO GHIERA cap only	SOLO GUARNIZIONE gasket only	SOLO O RING O ring only	PER UGELLI for spray tips	ORDINE MINIMO minimum order
80.618.38 (Nero/Black)	80.605.88	300.601.31	-	CVI - ID/IDK Lechler	10
84.618.51 (Nero/Black)	84.605.107	300.601.31 + 88.601.1	300.602.60	ATR - ATI	10
84.618.52 (Nero/Black)	84.605.107	300.601.31	-	TVI - ATF	10



CHIAVE QUICK CAPS QUICK CAPS TOOL



Peso: 90 g
Materiali: POM - acciaio inox
Impiego: per ghiere Quick Caps.

Weight: 90 g (3.17 oz)
Materials: POM - s. steel
Use: Quick Cap tool. For agriculture use.

COME SI ORDINA / HOW TO ORDER

CODICE
code

84.213.7